

<u>AN244</u>

Internal RC Oscillator Calibration

Author: Chris Valenti Microchip Technology Inc.

INTRODUCTION

Recently, Microchip has introduced a series of new PIC16 and PIC18 PICmicro[®] microcontrollers that have an on-board Internal RC Oscillator, capable of eight frequencies from 31 kHz to 8 MHz. These microcontrollers include the following devices:

- PIC16F818/819
- PIC16F87/88
- PIC18F1X20
- PIC18F2220/2320/4220/4320


The internal RC oscillator is configured and tuned by the OSCCON and OSCTUNE registers, respectively. The OSCCON register sets the frequency and contains the IOFS bit, which indicates when the frequency has stabilized after a frequency change in the OSCCON register. OSCTUNE is responsible for tuning the frequency within a range of +/-12 percent on the selected frequency. The upper range of tuning is 01h - 1Fh and the lower range is 20h - 3Fh, with center frequency at 00h. It is recommended to consult the device data sheet for further details.

The assembly code included in this application note (see Appendix A) is only applicable for a PIC16F819 microcontroller; however, with minor changes, the code can be ported over to the devices listed above. Having an internal RC oscillator eliminates the need for capacitors and an external crystal, resulting in production cost savings.

You may be wondering, "Why would it be necessary to calibrate the internal oscillator if it is supposed to come from the factory already calibrated?" Even though the internal oscillator is factory calibrated at 25°C, temperature variations in the operating environment must be considered. Since a change in frequency, as little as two to three percent, can corrupt serial communication, the information presented in this application note can help you avoid this issue by allowing frequency calibration over temperature.

The ability to calibrate the internal oscillator means that a known time-base must be established as a reference point. This time-base will be derived from a 32.768 kHz clock crystal connected to Timer1 (see Figure 1). Other fixed time-bases that can be used are AC line frequency (50 or 60 Hz).

FIGURE 1: TIMER1 OSCILLATOR WITH 32.768 KHZ XTAL



In this application note, we will be calibrating the 4 MHz tap of the internal oscillator. The calibration method will compare the time it takes for a specific number of instructions to occur over a defined period of Timer1. It is not mandatory to calibrate the internal oscillator at 4 MHz as Table 1 indicates; however, if you choose 4 MHz for calibration and your code requires a frequency change after calibration is complete, the other frequency chosen will be calibrated.

TECHNICAL DETAILS

Before going further, let us first establish several system numbers that will be important for understanding the techniques used in this application note. The values in Table 1 were derived from the base numbers shown below in Figure 1.

Knowing that 30.5 instructions can be executed within one Timer1 count, we can now determine if the oscillator requires calibration and whether it is too fast or too slow.

There are several variables that are required for this calibration approach. The first is the number of Timer1 counts. This number is subtracted from FFFFh to determine what value TMR1H:TMR1L will be loaded with. This is not a code-defined variable, but you may choose to define it as such. A defined constant, called calc_instr, is set by the user for the expected number of instructions that will be executed for a defined Timer1 interval established by the TMR1H:TMR1L value.

The second defined constant is f_delta_calc, which is set by the user according to their accuracy requirements. This number is the allowable difference between the calculated number of instructions expected (calc_instr) and the measured (mesrd instr) number of instructions executed.

As previously mentioned, Table 1 shows several of the available internal RC oscillator frequencies. For each of these frequencies, there are instruction execution times with +/-1% accuracy, and the calculated number of instructions for 25 Timer1 counts. The mesrd_instr variable increments until the Timer1 overflow flag is set. The f_delta_count, as mentioned previously, is the acceptable difference by mesrd_inst and calc_instr. By changing the value shown in the T1 CNTS column of Table 1, the following columns will yield different results. If the f_delta_count is increased, the calibration time is decreased, but accuracy will fall off.

TABLE 1: INTRC OSCILLATOR FACTORY CALIBRATION VALUES

INTRC Freq	Fosc/4	Τcγ (μs)	Tcy/T1 Count	Dri (%		Tcγ (μs) (Slow)	Tcy/T1 Count	Freq (+1%)	Tcγ(μs) (Fast)	Tcy/T1 Count	
8000000	2000000	0.500	61.036	1	1980000	0.505	60.426	2020000	0.495	61.646	
4000000	1000000	1.000	30.518	1	990000	1.010	30.213	1010000	0.990	30.823	Π
2000000	500000	2.000	15.259	1	495000	2.020	15.106	505000	1.980	15.412	
1000000	250000	4.000	7.630	1	247500	4.040	7.553	252500	3.960	7.706	

	T1 CNTS	Tcy Total (Slow)	Тсү Total	Tcy Total (Fast)	calc _instr	f_delta_count
_	25	1510.6	1525.90	1541.2	381.5	3.8
	25	755.3	762.95	770.6	190.7	1.9
	25	377.7	381.48	385.3	95.4	1.0
	25	188.8	190.74	192.6	47.7	0.5

EXAMPLE 1: CALIBRATION BASE NUMBERS

- Timer1 Clock Crystal: 32.768 kHz \rightarrow 1/32,768 = 30.5 μs period
- System Clock: 4 MHz \rightarrow Fosc/4 = 1 MHz core clock = 1 μ s Instruction time (TCY)
- 4 MHz @ +1% = 1.01 MHz core clock = .990 μs Tcy
- 4 MHz @ -1% = .990 MHz core clock = 1.01 μs Tcγ
- @ 4 MHz (1 μs TCY), 30.5 core instructions can be executed for one count of Timer1.

CODE DESCRIPTION

Before the calibration code is executed as shown in the flow diagram in Figure 2, the user must ensure that the 32.768 kHz clock crystal connected to Timer1 has adequate time to become stable. If this stability is not ensured, then the calibration routine will be driven from an inaccurate time-base. The required initialization is minimal; the internal oscillator is configured for 4 MHz via the OSCCON register. Timer1 is configured via T1CON for:


- 1:1 prescale
- Osc enabled
- Do not synchronize external clock input
- External clock from T1OSO
- Timer1 enabled

Upon entry into the calibration routine, the TMR1H:TMR1L registers are loaded with 0xFFE7h, which establishes 25 Timer1 counts until overflow. An incrementing loop is entered and exit only takes place when a Timer1 overflow occurs (TMR1IF = 1).

Next, the mesrd_instr variable is subtracted from the calc_instr constant to determine if the frequency is slower or faster than 4 MHz. Once this decision is made by a bit test on the carry flag, either the slower_freq or faster_freq subroutine will be entered. In both of these instruction sets, the current frequency is checked if it is acceptable for operation. This is determined by comparing the difference between mesrd_instr and calc_instr with the value of f_delta_count. If the result is acceptable, then the calibration is complete. If the result is unacceptable, the OSCTUNE register decrements or increments, depending on the speed of the measured frequency.

When the OSCTUNE register is modified, the new "tuned" values take approximately 256 μ s to become stable. Therefore, a delay (tune_delay) must be called before the frequency can be checked again. When the delay_temp variable is loaded with 0x57, the tune_delay loop will take up to 266 μ s @ 4 MHz.





CONCLUSION

The assembly code has been written as relocatable code so that it can easily be added to an existing application. The code usage is 56 words of program memory, 2 bytes of RAM and takes approximately 31 ms from start to finish. Although specific numbers have been used in this application, they may be different for other application requirements. TMR1H:TMR1L can be loaded with different values, which can speed up the calibration routine with less frequency sampling, or slow the routine with more sampling.

The f_delta_count value in this application is defined for +/-1 percent, but can be changed for 2 or 3 percent accuracy. These variables can be used in applications at the discretion of the user. Some applications may require that the OSCTUNE value after calibration be retained for RESET or POR conditions. This can be accomplished by storing the value in the PICmicro microcontroller's on-board EEPROM.

So that an organized starting point in your code development can be established, it is recommended that you create a spreadsheet file similar to that of Table 1. Doing this will also help in fine tuning the calibration boundaries to the application.

APPENDIX A: SOURCE CODE

Software License Agreement

The software supplied herewith by Microchip Technology Incorporated (the "Company") is intended and supplied to you, the Company's customer, for use solely and exclusively with products manufactured by the Company.

The software is owned by the Company and/or its supplier, and is protected under applicable copyright laws. All rights are reserved. Any use in violation of the foregoing restrictions may subject the user to criminal sanctions under applicable laws, as well as to civil liability for the breach of the terms and conditions of this license. THIS SOFTWARE IS PROVIDED IN AN "AS IS" CONDITION. NO WARRANTIES, WHETHER EXPRESS, IMPLIED OR STATU-

THIS SOFTWARE IS PROVIDED IN AN "AS IS" CONDITION. NO WARRANTIES, WHETHER EXPRESS, IMPLIED OR STATU-TORY, INCLUDING, BUT NOT LIMITED TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICU-LAR PURPOSE APPLY TO THIS SOFTWARE. THE COMPANY SHALL NOT, IN ANY CIRCUMSTANCES, BE LIABLE FOR SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES, FOR ANY REASON WHATSOEVER.

```
:*
     This code assumes the following conditions:
;*
           1. Config bits FOSC2:FOSC0 set to INTRC.
;*
;*
            2. INTOSC is configured for 4MHz system clock via OSCCON reg.
;*
;*
            3. Timer1 has been configured for 32.768kHz external crystal
;*
              and stable operation has been established.
:*
;*
     Call from main: call int rc cal
rc_cal.asm
;* FileName:
                P16819.inc, 16f819.lkr
16F819
;* Dependencies:
;* Processor:
;* MPLAB IDE
                 6.10.0.0
;* MPASM Tool Suite 1.10.0.0
;* Company:
                Microchip Technology, Inc.
;*
;* Software License Agreement
;*
;* The software supplied herewith by Microchip Technology Incorporated
;* (the "Company") for its PICmicro® Microcontroller is intended and
;* supplied to you, the Company's customer, for use solely and
;* software is owned by the Company and/or its supplier, and is
; ^{\star} protected under applicable copyright laws. All rights are reserved.
;* Any use in violation of the foregoing restrictions may subject the
;* user to criminal sanctions under applicable laws, as well as to
;* civil liability for the breach of the terms and conditions of this
;* license.
:*
;* THIS SOFTWARE IS PROVIDED IN AN "AS IS" CONDITION. NO WARRANTIES,
;* WHETHER EXPRESS, IMPLIED OR STATUTORY, INCLUDING, BUT NOT LIMITED
;* TO, IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A
;* PARTICULAR PURPOSE APPLY TO THIS SOFTWARE. THE COMPANY SHALL NOT,
;* IN ANY CIRCUMSTANCES, BE LIABLE FOR SPECIAL, INCIDENTAL OR
;* CONSEQUENTIAL DAMAGES, FOR ANY REASON WHATSOEVER.
;*
;* Author
                Date
                            Comment
    :*~~~
                Nov 19, 2002 Initial Release (V1.0)
;* Chris Valenti
;*
P=16F819
      list
      #include
                 <P16F819.INC>
      errorlevel
                 -302
#define
           calc instr
                     .190 ;calculated # of instructions
```

AN244

#define f delta calc .1 ;acceptable difference cal var UDATA SHR 0x20 mesrd_instr RES 1 ;measured # of instructions executed delay_temp RES 1 ;delay variable CODE 0x0005 cal int rc cal banksel TMR1H ;clear TIMER 1 interrupt flag ;clear loop count register bcf PIR1, TMR1IF clrf mesrd instr movlw 0xFF ;use 25 counts of Timer 1 movwf TMR1H movlw 0xE7 movwf TMR1L ;T1 starts count here incf mesrd instr,f ;increment btfss PIR1,TMR1IF ;has TMR1 overflowed ?? \$-2 goto ; NO, continue incrementing ;YES, start calibration count done banksel mesrd instr movf mesrd_instr,w sublw calc_instr ;calc_instr - mesrd_instr, find f_delta btfss STATUS,C ; Is the Frequency slow or fast ? goto slower freq ;mesrd count > calc count, freq is fast faster_freq goto ;mesrd count < calc count, freq is slow slower freq ; DECREASE FREQUENCY sublw 0xFF ;FF - w reg ;Check if freq is acceptable sublw f delta calc btfsc STATUS,C ;Is w reg > f delta calc? ;NO, calibration done! goto done banksel OSCTUNE decf OSCTUNE,F ;YES, decrease the frequency call tune_delay ;allow OSCTUNE change to take effect goto int_rc_cal ;calibrate again ; INCREASE FREQUENCY faster freq sublw f delta calc ;Check if freq is acceptable btfsc STATUS,C ;Is w_reg > f_delta_calc? goto done ;NO, calibration done! banksel OSCTUNE incf OSCTUNE, f ;YES, increase the frequency ;allow OSCTUNE to take effect call tune delay int_rc_cal goto ;calibrate again done return ; continue with main code GLOBAL int rc cal ; Function: tune delay ; ; Overview: This routine is used as a delay to allow the tuned value of ; OSCTUNE to take effect. >87 loaded into delay temp will yield ; a 266us delay @ 4MHz ; ; ; Input: None ; Output: None

	Sectior	n Info		
Section	Туре	Address	Location	Size(Bytes)
STARTUP	code	0x000000	program	0x00000a
cal	code	0x00005	program	0x000056
.cinit	romdata	0x00030	program	0x000004
main_c	code	0x000040	program	0x000012
.config	code	0x002007	program	0x000002
cal_var	udata	0x000020	data	0x000002

Program Memory Usage Start End ------ ------0x000000 0x000031 0x000040 0x000048 0x002007 0x002007 60 out of 2312 program addresses used, program memory utilization is 2%

	Symbols - S	Sorted by Ad	dress	
Name	Address	Location	Storage	File
int_rc_cal	0x000005	program	extern	C:\Program Files\MPLAB IDE\rc_cal.asm
_cal_000F	0x00000f	program	static	C:\Program Files\MPLAB IDE\rc_cal.asm
count_done	0x000010	program	static	C:\Program Files\MPLAB IDE\rc_cal.asm
slower_freq	0x000017	program	static	C:\Program Files\MPLAB IDE\rc_cal.asm
faster_freq	0x000020	program	static	C:\Program Files\MPLAB IDE\rc_cal.asm
done	0x000028	program	static	C:\Program Files\MPLAB IDE\rc_cal.asm
tune_delay	0x000029	program	static	C:\Program Files\MPLAB IDE\rc_cal.asm
_cal_002E	0x00002e	program	static	C:\Program Files\MPLAB IDE\rc_cal.asm
Start	0x000040	program	static	C:\Program Files\MPLAB IDE\main.asm
mesrd_instr	0x000020	data	static	C:\Program Files\MPLAB IDE\rc_cal.asm
delay_temp	0x000021	data	static	C:\Program Files\MPLAB IDE\rc_cal.asm

NOTES:

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products.

Information contained in this publication regarding device applications and the like is intended through suggestion only and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. No representation or warranty is given and no liability is assumed by Microchip Technology Incorporated with respect to the accuracy or use of such information, or infringement of patents or other intellectual property rights arising from such use or otherwise. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, KEELOQ, MPLAB, PIC, PICmicro, PICSTART, PRO MATE and PowerSmart are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


FilterLab, microID, MXDEV, MXLAB, PICMASTER, SEEVAL and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Accuron, dsPIC, dsPICDEM.net, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, microPort, Migratable Memory, MPASM, MPLIB, MPLINK, MPSIM, PICC, PICkit, PICDEM, PICDEM.net, PowerCal, PowerInfo, PowerTool, rfPIC, Select Mode, SmartSensor, SmartShunt, SmartTel and Total Endurance are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

Serialized Quick Turn Programming (SQTP) is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2003, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.





Microchip received QS-9000 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona in July 1999 and Mountain View, California in March 2002. The Company's quality system processes and procedures are QS-9000 compliant for its PICmicro® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, non-volatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: 480-792-7627 Web Address: http://www.microchip.com

Rocky Mountain

2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7966 Fax: 480-792-4338

Atlanta

3780 Mansell Road, Suite 130 Alpharetta, GA 30022 Tel: 770-640-0034 Fax: 770-640-0307

Boston

2 Lan Drive, Suite 120 Westford, MA 01886 Tel: 978-692-3848 Fax: 978-692-3821

Chicago

333 Pierce Road, Suite 180 Itasca, IL 60143 Tel: 630-285-0071 Fax: 630-285-0075

Dallas

4570 Westgrove Drive, Suite 160 Addison, TX 75001 Tel: 972-818-7423 Fax: 972-818-2924

Detroit

Tri-Atria Office Building 32255 Northwestern Highway, Suite 190 Farmington Hills, MI 48334 Tel: 248-538-2250 Fax: 248-538-2260

Kokomo

2767 S. Albright Road Kokomo, Indiana 46902 Tel: 765-864-8360 Fax: 765-864-8387

Los Angeles

18201 Von Karman, Suite 1090 Irvine CA 92612 Tel: 949-263-1888 Fax: 949-263-1338

San Jose

Microchip Technology Inc. 2107 North First Street, Suite 590 San Jose, CA 95131 Tel: 408-436-7950 Fax: 408-436-7955

Toronto

6285 Northam Drive, Suite 108 Mississauga, Ontario L4V 1X5, Canada Tel: 905-673-0699 Fax: 905-673-6509

ASIA/PACIFIC

Australia

Microchip Technology Australia Pty Ltd Suite 22, 41 Rawson Street Epping 2121, NSW Australia

Tel: 61-2-9868-6733 Fax: 61-2-9868-6755 China - Beijing

Microchip Technology Consulting (Shanghai) Co., Ltd., Beijing Liaison Office Unit 915 Bei Hai Wan Tai Bldg. No. 6 Chaoyangmen Beidajie Beijing, 100027, No. China Tel: 86-10-85282100 Fax: 86-10-85282104 China - Chengdu

Microchip Technology Consulting (Shanghai) Co., Ltd., Chengdu Liaison Office Rm. 2401-2402, 24th Floor, Ming Xing Financial Tower No. 88 TIDU Street Chengdu 610016, China Tel: 86-28-86766200 Fax: 86-28-86766599

China - Fuzhou

Microchip Technology Consulting (Shanghai) Co., Ltd., Fuzhou Liaison Office Unit 28F, World Trade Plaza No. 71 Wusi Road Fuzhou 350001, China Tel: 86-591-7503506 Fax: 86-591-7503521

China - Hong Kong SAR

Microchip Technology Hongkong Ltd. Unit 901-6, Tower 2, Metroplaza 223 Hing Fong Road Kwai Fong, N.T., Hong Kong Tel: 852-2401-1200 Fax: 852-2401-3431

China - Shanghai Microchip Technology Consulting (Shanghai)

Co., Ltd. Room 701, Bldg. B Far East International Plaza No. 317 Xian Xia Road

Shanghai, 200051 Tel: 86-21-6275-5700 Fax: 86-21-6275-5060

China - Shenzhen

Microchip Technology Consulting (Shanghai) Co., Ltd., Shenzhen Liaison Office Rm. 1812, 18/F, Building A, United Plaza No. 5022 Binhe Road, Futian District Shenzhen 518033, China Tel: 86-755-82901380 Fax: 86-755-82966626

China - Qingdao

Rm. B503, Fullhope Plaza, No. 12 Hong Kong Central Rd. Qingdao 266071, China Tel: 86-532-5027355 Fax: 86-532-5027205 India Microchip Technology Inc. India Liaison Office **Divyasree Chambers** 1 Floor, Wing A (A3/A4) No. 11, O'Shaugnessey Road Bangalore, 560 025, India Tel: 91-80-2290061 Fax: 91-80-2290062

Japan

Microchip Technology Japan K.K. Benex S-1 6F 3-18-20, Shinyokohama Kohoku-Ku, Yokohama-shi Kanagawa, 222-0033, Japan Tel: 81-45-471- 6166 Fax: 81-45-471-6122 Korea Microchip Technology Korea 168-1, Youngbo Bldg. 3 Floor Samsung-Dong, Kangnam-Ku Seoul, Korea 135-882 Tel: 82-2-554-7200 Fax: 82-2-558-5934 Singapore Microchip Technology Singapore Pte Ltd. 200 Middle Road #07-02 Prime Centre Singapore, 188980 Tel: 65-6334-8870 Fax: 65-6334-8850 Taiwan Microchip Technology (Barbados) Inc., Taiwan Branch 11F-3, No. 207 Tung Hua North Road Taipei, 105, Taiwan Tel: 886-2-2717-7175 Fax: 886-2-2545-0139 EUROPE Austria Microchip Technology Austria GmbH Durisolstrasse 2 A-4600 Wels Austria Tel: 43-7242-2244-399 Fax: 43-7242-2244-393 Denmark Microchip Technology Nordic ApS Regus Business Centre Lautrup hoj 1-3 Ballerup DK-2750 Denmark Tel: 45 4420 9895 Fax: 45 4420 9910 France Microchip Technology SARL Parc d'Activite du Moulin de Massy 43 Rue du Saule Trapu Batiment A - ler Etage 91300 Massy, France Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 Germany Microchip Technology GmbH Steinheilstrasse 10 D-85737 Ismaning, Germany Tel: 49-89-627-144 0 Fax: 49-89-627-144-44 Italy Microchip Technology SRL Centro Direzionale Colleoni Palazzo Taurus 1 V. Le Colleoni 1 20041 Agrate Brianza Milan, Italy Tel: 39-039-65791-1 Fax: 39-039-6899883 United Kingdom

Microchip Ltd 505 Eskdale Road Winnersh Triangle Wokingham Berkshire, England RG41 5TU Tel: 44 118 921 5869 Fax: 44-118 921-5820

12/05/02